



Well Inspection Report

CLIENT: City of North Las Vegas
 ADDRESS: Unknown
 PHONE: 702-249-1227
 JOB LOCATION: 4301 Alexander Road
 GPS LOCATION: Latitude: N 36° 13' 54.3" Longitude: W 115° 11' 43.5"

WELL NUMBER: #3 JOB NUMBER: 50-0426

SURVEYED BY: Jeff Conner DATE: 20-Sep-06

REVIEWED BY: WATER LEVEL: 144' 5"

WATER CONDITION: Clear TOTAL DEPTH: 930'

CASING DIAMETER: 15.25" ID SURVEY DEPTH: 916' 6"

*All Depths Shown are relative to the center of the side camera perspective.

DEPTH	REMARKS		
5 - 144'	Casing appears to have mild scale and growth.	Perforation:	
144 - 191'	Oil above static water level.	Full/Flo Louver	704 - 911'
191 - 626'	Casing appears to have mild growth.		
625 - 700'	Casing appears to have increased growth.		
700 - 916'	Casing appears to have moderate scale and growth over perforations.		
916' 6"	Camera enters fill to side perspective and is stopped.		

